

STATUS OF HIGH SECURITY REGISTRATION PLATE (HSRP) MANUFACTURER AT ARAI AS ON 12.12.2017

1. FACILITY EXISTS AND COP STATUS

Sr. No.	Name of the Company and registered office	Plant address	Status of facility and CoP [Stipulated Period (whichever is earlier) for C.O.P]
1	<p>Utsav Safety Systems (P) Ltd. F-48, Mayapuri Industrial Area, Phase II, New Delhi – 110064 Tel : 09811612977 E-mail: info@utsavhsrp.com Contact Person: Mr. Mahesh Malhotra</p>	<p>Plant 1 Plot No. 3A, Phase IV, Gowalthai Ind. Area, Distt.: Bilaspur – 174 201 (HP)</p> <p>Plant 2 M/s. Utsav Safety Systems (P) Ltd., Sila Senduri Chopra, Chowki Gate, NH-31, Korai Bari, Changsari, Dist: Kamrup, Assam – 781 031.</p>	<ul style="list-style-type: none"> ➤ Upto 15 lacs from 01st June 2018. ➤ 01st June 2018 to 31st May 2020. ➤ Upto 15 lacs from 1st April 2018. ➤ 1st April 2018 to 31st March 2020.
2	<p>Celex Technologies Pvt. Ltd. 'Haute Street' Building, 86A, Topsia Road, Unit # 702, 7th Floor Kolkata 700 046, West Bengal, India Ph: +91-33-40033222 Mobile : +91-9874799225 Fax: +91-33-40033000 Email : celextech@gmail.com; info@celex.co.in Contact Person: Sandeep Agarwal Website : www.celex.co.in</p>	<p>Arupot Village, Dhapa MathPukur, Behind P. G. Chandra Gardens Off Basanti Highway Kolkata – 700 105</p>	<ul style="list-style-type: none"> ➤ Upto 15 lacs from 2nd June 2018. ➤ 2nd June 2018 to 1st June 2020.
3	<p>Akruti Safeguard Systems Pvt. Ltd. 104, Akruti Annexe Bldg., Next to Akruti Trade Center, Road No. 7, Marol MIDC, Andheri (E), Mumbai 400093. Tel.: (022) 28311403 Fax: (022) 39166801 Email: info@hsrpindia.com kamlesh@hsrpindia.com</p>	<p>D-89/3, TTC Industrial Area, MIDC Turbhe, Navi Mumbai 400705.</p>	<ul style="list-style-type: none"> ➤ Upto 15 lacs from 4th January 2017 ➤ 4th January 2017 to 3rd January 2019
4	<p>Promuk Hoffmann International Limited 6-3-649/5, 2nd Floor, Chakkilam House, Somajiguda Hyderabad - 500 082 Ph: 040 -66668777, 66669777 email: utlhyd@utlindia.com</p>	<p>Plot No:1,IDA, Kothur, Mehaboobnagar Dist. Andhra Pradesh</p>	<ul style="list-style-type: none"> ➤ CoP is under process.
5	<p>Hind Industries Limited. B3, Friends Colony (West) Main Mathura Road New Delhi – 110 035 E-mail: hsrp_kapoor@rediffmail.com Cell: 9810026562 Contact Person: Mr. Ulfat Rai</p>	<p>Khasra No. 137, Village Tipra, Teshsil Kasauli, Dist Solan, Himachal Pradesh</p>	<ul style="list-style-type: none"> ➤ Facility was exists on September 2006 ➤ CoP is not valid as on date

2.0 FACILITY DOES NOT EXIST

Sr. No.	Name of the Company	Status of facilities and CoP
1	<p>Omish Traders. Social Compound, Marol Pipelin, Andheri - Kurla Road, Andheri East, <u>Mumbai – 400 059, Maharashtra.</u> Ph.: 8253170 / 71 Fax: 022-8316261 Contact Person: Mr. Vasant Shetty.</p>	<p>➤ As per ARAI record, facility does not exist and manufacturer did not approach for CoP or factory inspection.</p>
2	<p>Metro Wilhelm Grewe (India) Lt B-92, Mayapuri Industrial Area, Phase - 1, <u>New Delhi – 110 064, Delhi.</u> Ph.: 5497545 / 46 Fax: 91-11-5132440, E-mail: <u>contact@metroroadsystems.com</u> Contact Person: Mr. Sachin Bhatiya - Director.</p>	<p>➤ As per ARAI record, facility does not exist and manufacturer did not approach for CoP or factory inspection.</p>
3	<p>M/s. D. D. Licence Plates Div. Of D. D. Ind. Ltd. F1/9. Okhla Industrial Area Phase – I New Delhi – 110020 Tel.: No.: 91-11-6372222 Fax.: 6813518 Email: <u>dd@ddindustries.net</u></p>	<p>➤ As per ARAI record, facility does not exist and manufacturer did not approach for CoP or factory inspection.</p>
4	<p>M/s. Emperor Granites Pvt. Ltd. 19, 20 Press Complex, M. P. Nagar, Bhopal, Madhya Pradesh Ph.: 09425111772, 09425304077 0755-2553759 Email: <u>emperorganites@yahoo.com</u> Contact Person: K .S. Thakur and Arun Dixit</p>	<p>➤ As per ARAI record, facility does not exist and manufacturer did not approach for CoP or factory inspection.</p>
5	<p>M/s. Signs India Ltd. 810 (Old 406), Anna Salai, Mount Road, Nandanam, <u>Chennai – 600 035, Tamilnadu.</u> Ph.: 4330857 / 4331084. E-mail: <u>singsindia@vsnl.com</u> Contact Person: Mr. Thomas Cherian. Certificate cleared on: 02.06.03</p>	<p>➤ Facility exists as per the initial document submitted at the time of type approval, but not offered for site assessment, ARAI considered that the facility does not exist.</p>

FACILITY DOES NOT EXIST cont.....

Sr. No.	Name of the Company	Status of facilities and CoP
6	Rayson's Mid Road Sign Craft Pvt. Ltd. 39-A, First floor, B. J. B. Nagar Bhubaneswar-751014 Tel: 314304, Fax.: 314305 Email: skjainc@yahoo.com Contact Person: Mr. S. K. Jain, Director 9433089530	➤ As per ARAI record, facility does not exist and manufacturer did not approach for CoP or factory inspection.
7	M/s. Road Sketch Pvt. Ltd. Flat No. 80, M.I.G. Flats, Loni Road, Shahdara, Delhi – 110 032 (INDIA). Ph. No.: 011-23350466/7 Email: roadsketch@uranussolutions.co . Contact Person.: Mr. K. D. Pandey	➤ As per ARAI record, facility does not exist and manufacturer did not approach for CoP or factory inspection.
8	M/s. Avantika Elcon Pvt. Ltd. A-22, Sector 7, Noida, Uttar Pradesh - 201301 Tel.: (011) 26316691, Fax: (011) 26928120 Email: info@aelcon.net, cgulati2006@gmail.com Contact Person : Mr. Chetan Gulati	➤ As per ARAI record, facility does not exist and manufacturer did not approach for CoP or factory inspection.
9	Great Saturn Intelligence and security Agency Pvt. Ltd. 4, Vaswani Mansion 120, Dinshaw Vachha Road, Churchgate, Mumbai – 400 020 TEL: 022-22880000, Cell :9869307081 Fax: 022-22040000. Email: greatsaturn@vsnl.net	➤ As per ARAI record, facility does not exist and manufacturer did not approach for CoP or factory inspection.
10	M/s. 3M India Ltd. 48-51, Electronics City, Hosur Road , Bangalore – 560100. Office Phone: 91 80 3914 3405 Mobile: 91 9741896655 Fax: 91 80 28520157 Email: njtahir1@mmm.com Contact Person: Tahir Naqvi	➤ As per ARAI record, facility does not exist and manufacturer did not approach for CoP or factory inspection.
11	M/s. RPP Infra Projects Ltd., S F No. 454, Raghupathynaiken Palayam, Poondyrai Road, Erode – 638 002 Ph: +91 424 2259022 Fax: +91 424 2253130 shankar@rppi.com Mr. S. Shankar, Manager Projects	➤ As per ARAI record, facility does not exist and manufacturer did not approach for CoP or factory inspection.